



R.	Zone	R.O.no.	Sign./Date	Status	Sign.	Date
				Constr.	PT	07Dec06
				Drawn by	PT	07Dec06
				Checked	EGJ	07Dec06
				Prot. rel.		
				Prod. rel.	EGJ	07Dec06


Frank Mohn AS
STARTER DOL WIRING DIAGRAM 1


This drawing is our property. It is not to be traced, copied or published without our written consent, nor to be misused in any way.
 Replaces:
0222-5639-301
 Replaced by:



X1: 24VDC
X2: 220VAC



R.	Zone	R.0.no.	Sign./Date	Status	Sign.	Date
				Constr.	PT	07Dec06
				Drawn by	PT	07Dec06
				Checked	EGJ	07Dec06
				Prot. rel.		
				Prod. rel.	EGJ	07Dec06

 Frank Mohn AS	This drawing is our property. It is not to be traced, copied or published without our written consent, nor to be misused in any way.
STARTER DOL WIRING DIAGRAM 2	
Replaced by:	